

# KC70-1.2.5 & 1.2.6

Welding Symbols for Tack and Full Penetration

