Troubleshooting Guide

Problem	Cause	Solution
Water flow is reduced	Aerator is clogged with debris	Remove aerator and clean screen
	Supply line valve is partially closed	Open supply line valve fully
Water leaks from base of spout	Loose connection nut	Tighten connection nut with wrench
	Worn O-ring	Replace O-ring
Water leaks from handle	Worn cartridge	Replace cartridge
Handle is stiff	Mineral buildup on cartridge	Soak cartridge in vinegar overnight
Water temperature fluctuates	Hot water supply is low	Wait for hot water supply to recover

ATKINSON BELLE

Model 4400 Series

Installation, Operation, and Maintenance Instructions