
ASSEMBLY INSTRUCTIONS

KINCAID®
SOLID WOOD SINCE 1946

69-1630 END TABLE



69-1630

HARDWARE LIST			
ITEM	DRAWINC	DESCRIPTION	Q' TY
A		Glass pad (Ø12*3mm)	4PCS

Caution: Do not over tighten any bolts during assembley.

1. Attach the glass pad(A) to the top and place the glass top. (Figure 1)

Glass
23 7/8" x 15 1/16" W
Tempered 1/4"T
EDGES BEVELED





Figure 1

ASSEMBLY INSTRUCTIONS

KINCAID®
SOLID WOOD SINCE1946

69-1433 RECT COCKTAIL TABLE



69-1433

HARDWARE LIST			
ITEM	DRAWING	DESCRIPTION	Q'TY
A		Bolt (Ø1/4"*3/4")	12PCS
B		Spring Washer (Ø1/4")	12PCS
C		Flat Washer (Ø1/4*Ø16mm)	12PCS
D		Allen Wrench (4mm)	1PC

Caution: Do not over tighten any bolts during assembley.

1. Attach the support to the side frame using bolt (A), spring washer (B), flat washer (C) and tighten with allen wrench(D). (Figure 1)
2. Attach the metal frame to the top using the bolt (A), spring washer (B), flat washer (C) and tighten with allen wrench (D). (Figure 2)




Figure 1





Figure 2

ASSEMBLY INSTRUCTIONS

KINCAID®
SOLID WOOD SINCE1946

69-1430 END TABLE



69-1430

HARDWARE LIST			
ITEM	DRAWING	DESCRIPTION	Q' TY
A		Bolt (Ø1/4"*3/4")	8PCS
B		Spring Washer (Ø1/4")	8PCS
C		Flat Washer (Ø1/4*Ø16mm)	8PCS
D		Allen Wrench (4mm)	1PC

Caution: Do not over tighten any bolts during assembley.

1. Attach the legs to the top using the bolt (A), spring washer (B), flat washer (C) and tighten with allen wrench (D). (Figure 1)





Figure 1

ASSEMBLY INSTRUCTIONS

KINCAID®
SOLID WOOD SINCE 1946

69-1330 END TABLE



69-1330

HARDWARE LIST			
ITEM	DRAWING	DESCRIPTION	Q' TY
A		Bolt (Ø1/4"*5/8")	22PCS
B		Spring Washer (Ø1/4")	22PCS
C		Flat Washer (Ø1/4"*Ø16mm)	22PCS
D		Allen Wrench (4mm)	1PC

Caution: Do not over tighten any bolts during assembley.

1. Attach the strechers to the side frame using bolt (A) , spring washer (B), flat washer (C) and the allen wrench (D). (Figure 1).

2. Attach the metal frame to the wood top using bolt (A), spring washer (B), flat washer (C) and the allen wrench (D). (Figure 2).

