



REVISION HISTORY			
REV	DESCRIPTION	DATE	APPROVED
A	**Original Release**	8/9/2016	J.H.P.
B	Narrowed window to 1mm, enlarged side circles to 5mm, added magnets for assembly drawing	9/8/2017	J.H.P.









Toyota 989A (Tacoma) PRF Top Check Fixture			
PART NUMBER	**DESCRIPTION**	**PRICE (each)**	**MOQ**
78-8137-9655-0	989A PRF Top Check Fixture (RF)	$545	2
78-8137-9656-8	989A PRF Top Check Fixture (LF)		
78-8137-9657-6	989A PRF Top Check Fixture (RR)		
78-8137-9658-4	989A PRF Top Check Fixture (LR)		
Prices as of 9/8/2017 and valid for 6 months. Subject to change without notice thereafter.			
Lead time on fixtures is 45 days.			
Subject to Terms of Sale at http://TINYURL.COM/D5YBVOL			

NOTES:
> (LF) Top Check Fixture is mirror image of (RF)
> (LR) Top Check Fixture is mirror image of (RR)
> Install four 3M 78-8137-3400-7 (.25x.25) magnets flush with vehicle contact surfaces
> Include lot # on fixture label

Automotive Division
Equip. Dev. & Design Svc.
3M Center, 230-1G-27
St. Paul, MN 55144-1000

This document contains information which is proprietary to 3M. No reproduction or publication of the document in whole or in part shall be made without written authorization from 3M.

Title
989A PRF Top Check Fixture (RF)

Drawing Number	Drawn By	Date
78-8137-9655-0	**John H. Peterson**	**9/8/2017**

CAD File Name
78-8137-9655-0_989A_PRF_Top_Check_Fixture_(RF)_revB