

Processing Procedure Dual Cover® Thermal Spread & Insulite Blanket

PROCESSING REQUIREMENTS

- A. Formula: This formula is only a guideline. Alterations should be made at the discretion of the laundry professional, based on specific requirements, supplies, equipment and experience.

	OPERATION	TIME	WATER LEVEL	TEMP.	SUPPLIES
1.	Flush	2 min.	High	100°F	--
2.	Break	6 min.	Low	160°F	Nonionic Detergent / Alkali
3.	Suds	10 min.	Low	160°F	Detergent
4.	Bleach*	8 min.	Low	160°F	Sodium Hypochlorite (100 ppm Target) Target pH of 10.2
5.	Rinse	2 min.	High	145°F	--
6.	Rinse	2 min.	High	130°F	--
7.	Rinse	2 min.	High	115°F	--
8.	Sour/Softener	5 min.	Low	100°F	Sour to pH of 5.5-6.5

Tumble dry at 160°F.

*Use bleach cycle only on color natural and white.