3M Neoprene Contact Adhesive 5 (Green and Light Yellow)

Technical Data		February, 2015			
Product Description	3M [™] Neoprene Contact Adhesive 5 is a sprayable contact adhesive which may be used to bond many high-pressure plastic laminates to wood, particle- board, metal and other surfaces.				
Features	• Sprayable.				
	• Fast drying.				
	• 60 minute bonding range.				
	• Excellent resistance to plastic flow (creep).				
Special Note	When bonding wood venered environmental conditions, adhesive type and top coat responsibility to thoroughl veneers. It is also recommen- and industry guidelines.	ers, success is dependent on many variables such as bonding process, type of base material, type of veneer, finishing systems to name a few. It is the user's y test any adhesive for its suitability in bonding wood nded to follow the veneer manufacturers recommendation			
Typical Physical Properties	Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.				
	Viscosity (approx.)	175-350 cps			
	Brookfield Viscometer	RVF #2 spindle @ 20 rpm @ 80°F (27°C)			
	Solids (by wt.)	18-21%			
	Base	Polychloroprene			
	Color	Green, Light Yellow			
	Net Weight (approx.)	6.4-6.8 lbs./gal.			
	Flash Point (TCC)	-14°F (-25°C)			
	Solvent	Petroleum distillate, acetone, toluene and n-hexane			
	Coverage (approx.)	233 sq. ft. per gallon (@ 2.5 gms./ft. ² dry wt.)			

$3M^{\text{TM}}$ Neoprene Contact

Adhesive 5 (Green and Light

Yellow)

Handling/ Directions For Use

ApplicationInformationNote: Read and follow precautions before using this product.

Surface Preparation

- 1. For best results all surfaces to be bonded should be dry and free from dirt, dust, oil, loose paint, wax, grease, etc.
- 2. Oil, grease and other contaminants can be removed by wiping with a solvent such as methyl ethyl ketone.*
- 3. If used for decorative laminate, laminate should have reached moisture equilibrium for the shop conditions.

Working Temperature

- 1. The temperature of the adhesive and surfaces to be bonded should be at 65°F (18°C) or above.
- 2. Warm the can of adhesive by placing in a warm room, not in stove, oven or other possible ignition source.
- 3. If the room must be warmed, turn off the heater before opening container.
- 4. Leave heater off until all vapors are gone.

Application

- 1. Stir thoroughly before using.
- 2. Apply adhesive generously in a uniform film on both surfaces with either a fiber or animal hair brush, or pour and spread with paint roller (solvent resistant texturing type).
- 3. Porous surfaces may require 2 coats of adhesive.
- 4. A glossy film when completely dry indicates adequate adhesive.
- 5. Dull spots after drying indicate not enough adhesive; these spots must have another coat.

Assembly

- 1. Allow to dry until adhesive is no longer tacky (5-10 minutes).
- 2. Position surfaces carefully before assembly.
- 3. No adjustment is possible after contact.
- 4. Spacers such as dowels or strips of laminate, may be used to prevent premature adhesive/adhesive contact and bonding.
- 5. Slide out the spacers and apply uniform pressure, working toward the edges.
- 6. A 3 in. roller used with maximum body pressure should be used to help ensure adequate contact and bonding, especially on the edges.
- 7. Bonded assemblies can be machined, trimmed or finished immediately after bonding.

Drying Time

1. Drying time depends on temperature, humidity, air movement and porosity of materials bonded.

Cleanup

- 1. Excess adhesive may be removed with a solvent such as methyl ethyl ketone.*
- *When using solvents, extinguish all ignition sources, including pilot lights, and follow manufacturer's precautions and directions for use.

3M[™] Neoprene Contact Adhesive 5 (Green and Light Yellow)

Application Equipment Suggestions	 Note: Appropriate application equipment enhances adhesive performance. We suggest the following application equipment for the user's evaluation in light of the user's particular purpose and method of application. 1. Pumping: A 2:1 divorced design pump is suggested. Packings and glands, in contact with the adhesive, should be PTFE. 						
	Spray Gun	Air Cap	Fluid Tip	Atomizing Air Pressure	Approximate Air Requirement*	Fluid Flow**	
	Binks 62, 2001, 95	66PH	63BSS (.046")	85 psi	24 CFM	7.5 fl. oz./min.	
	DeVilbiss JGA, MSA	777	FX (.042")	85 psi	24 CFM	6 fl. oz./min.	
	Note: These adhesives are not recommended for Airless Spraying. *3 H.P. Compressor for intermittent use. 5 H.P. Compressor for continuous use. **To Measure Fluid Flow: Pressurize fluid source only; pull trigger, flow material into measuring device for 60 seconds, increase or decrease fluid source pressure to obtain desired fluid flow.						
	4. Hoses: All material hoses should be nylon or PVA lined.						
	5. Brush/Rol	ller: Typi	ical brushes/rolle	rs designed fo	or oil-based paint m	ay be used.	
	Typical Adhesive Performance	Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.					
	Characteristics	Pool Strongt	n Conv	vas/Staal			

Peel Strength – Canvas/Steel

Time @ 75°F (24°C)	Test Temp.	Value (Ibs./in. width)
1 day	75°F (24°C)	10
3 days	75°F (24°C)	12
5 days	75°F (24°C)	14
7 days	75°F (24°C)	18
2 weeks	75°F (24°C)	18
3 weeks	75°F (24°C)	19
after 3 weeks	-30°F (-34°C)	16.5
after 3 weeks	180°F (82°)	7

Overlap Shear Strength – 1/8" Birch/Birch

Time @ 75°F (24°C)	Test Temp.	Value (Ibs./in. width)
2 weeks	75°F (24°C)	480
3 weeks	75°F (24°C)	482
after 3 weeks	-30°F (-34°C)	1060
after 3 weeks	180°F (82°)	65
after 3 weeks	225°F (107°C)	38

$3M^{{}^{\rm \tiny TM}}\, Neoprene\ Contact$

Adhesive 5 (Green and Light Yellow)

Storage	Best storage temperature is 60-80°F (16-27°C). Higher temperatures reduce normal storage life. Lower temperatures cause increased viscosity of a temporary nature. Rotate stock on a "first in, first out" basis.
Shelf Life	When stored at the recommended temperature in the original, unopened container, this product has a shelf life of 15 months.
Precautionary Information	Refer to Product Label and Material Safety Data Sheet for health and safety information before using this product. For additional health and safety information, call 1-800-364-3577 or (651) 737-6501.
Technical Information	The technical information, recommendations and other statements contained in this document are based upon tests or experience that 3M believes are reliable, but the accuracy or completeness of such information is not guaranteed.
Product Use	Many factors beyond 3M's control and uniquely within user's knowledge and control can affect the use and performance of a 3M product in a particular application. Given the variety of factors that can affect the use and performance of a 3M product, user is solely responsible for evaluating the 3M product and determining whether it is fit for a particular purpose and suitable for user's method of application.
Warranty, Limited Remedy, and Disclaimer	Unless an additional warranty is specifically stated on the applicable 3M product packaging or product literature, 3M warrants that each 3M product meets the applicable 3M product specification at the time 3M ships the product. 3M MAKES NO OTHER WARRANTIES OR CONDITIONS, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OR CONDITION OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR ANY IMPLIED WARRANTY OR CONDITION ARISING OUT OF A COURSE OF DEALING, CUSTOM OR USAGE OF TRADE. If the 3M product does not conform to this warranty, then the sole and exclusive remedy is, at 3M's option, replacement of the 3M product or refund of the purchase price.
Limitation of Liability	Except where prohibited by law, 3M will not be liable for any loss or damage arising from the 3M product, whether direct, indirect, special, incidental or consequential, regardless of the legal theory asserted, including warranty, contract, negligence or strict liability.
	This Industrial Adhesives and Tapes Division product was manufactured under a 3M quality system registered to ISO 9001:2000 standards.

ЗМ

Industrial Adhesives and Tapes Division

3M Center, Building 225-3S-06 St. Paul, MN 55144-1000 800-362-3550 • 877-369-2923 (Fax) www.3M.com/Adhesives



3M is a trademarks of 3M Company. Printed in U.S.A. ©3M 2015 78-6900-9881-5 (9/10)