








ASSEMBLY INSTRUCTIONS

MONSANTO C TABLE


PART LIST :-

NO.	DESCRIPTION	IMAGE	QTY
A	METAL BASE RING		1
B	METAL POLE		1
C	METAL TOP		1
D	SMALL SCREWS		3
E	LARGE SCREWS		4
F	ALLEN KEY		1


STEP:- 1




STEP:- 2




STEP:- 3



STEP:- 4



STEP:- 5



ASSEMBLED

