FIREPOINT® C-O-B STRIP LED HEADLAMP

To Charge the Light:

- 1. Lift the cover of the headlamp to expose the USB-C charging port.
- 2. Plug the USB-C cable firmly into the slot
- 3. Insert other end into USB ready power source for charging

NOTE: Recharge the light every 3-6 months if not in use for long periods of time. Turn off the light during charging.

3.7V 1800mAh Li-Polymer Battery:

Charging Time: 6 hours

500 (high), 100 (low) Lumens:



DISPOSAL AND RECYCLING OF LITHIUM-POLY BATTERIES

This light contains lithium poly batteries in a sealed compartment. Please dispose of properly.

Follow all state and federal laws applicable to the disposal disposal or recycling of lithium-poly batteries. For more info contact government, recycling, waste management or retailers in your area, Information online can be found at: www.batteryrecycling.com

↑ WARNING!

LED BULBS

LED bulbs are very bright and can cause serious injury to your eyes Do not stare directly into the LED bulb beam

Do not point or direct this LED device into your eves

BATTERIES

Do not mix old and new batteries with product

Do not mix alkaline batteries with carbon zinc or rechargeable batteries

Do not install hatteries backwards

Do not throw batteries into fire that can cause battery to explode or leak causing personal injury

Remove batteries when storing product for a long period of time