










# ASSEMBLY INSTRUCTION

ITEM: 7228-80178-85 Jack O'bein Long Skinny Console


Thank you for purchasing this quality product. Be sure to unpack carefully looking for small parts which may have come loose during shipment.

Read all instruction and study the drawing carefully before starting the assembly process.

HARDWARE PACK					PARTS LIST			
NO.	DRAWING	DESCRIPTION	SIZE	Q'TY	NO.	DRAWING	DESCRIPTION	Q'TY
A		Bolt	$\frac{5}{16}$ "x25MM	14 PCS	1		Side Leg	4 PCS
B		Lock Washer	$\frac{5}{16}$ "	26 PCS	2		Center Leg	2 PCS
C		Flat Washer	$\frac{5}{16}$ "	26 PCS	3		Bottom Short Stretcher	3 PCS
D		Allen Wrench	73*29*5mm	1 PC	4		Bottom Long Stretcher	4 PCS
E		Bolt	$\frac{5}{16}$ "x60MM	12 PCS	5		Table Top	1 PC



Adjust leveler if needed to level table on uneven floor.




Thank you for purchasing this quality product. Be sure to unpack carefully looking for small parts which may have come loose during shipment.

Read all instruction and study the drawing carefully before starting the assembly process.

**Note:**

Please follow numbers on legs and corner blocks when assembling legs to the table.

**Step 2:** Attach bottom short stretchers (3) and bottom long stretchers (4) with flat washers (C), lock washers (B) and bolts (A), fully tighten them with allen wrench (D).



**Step 1:** Attach legs (1) & center leg (2) to table top (5) by using flat washers (C), lock washers (B) and bolts (E), do not fully tighten bolts (E) at this step.