




TECHNICAL SERVICE BULLETIN

Model: BVML500
Firmware Update
iOS 9.1 Display Fix

Step 1

Unzip the file, and copy into an empty USB flash drive.

***USB Drive must not contain any other data (i.e. files, folders, music, etc...)**



Step 2 & 3

Insert the USB flash drive into the USB Port


Power **ON** the BVML500

Update will start automatically

***Do Not Power OFF the unit while its updating**




The update will take anywhere from 5-7 min.

Several screens will be displayed during this process.



Step 3 Continued....

Several screens will be displayed during this process.



Step 4

The BVML500 will boot up after the update is complete.....

Once the BVML500 has started and is on this screen, remove the USB drive.

Then press the RESET button. The BVML500 will restart and load. Update is now complete.

V2.0.0 will be displayed

