



Hardware List

Α	e)mn	M6*10	Bolt	20	pcs
В		M6*35	Bolt	4	pcs
С		M4	Hex Key	1	рс

The hardware quantities listed above are required for proper assembly. Some extra hardware may also have been included.





Attach part (3, 4) to part (1) using bolt (B) with hey key (C).

