

Helps workers see clearly longer.


See the science behind 3M™ Anti-Fog Coatings.



Workers in environments with significant temperature changes are most likely to experience fogging


Fogging on protective eyewear lenses can obscure a workers field of vision, potentially leading to a workplace injury due to poor visibility. Excessive fogging can also prompt a worker to remove their protective eyewear, leaving eyes exposed to workplace hazards.

How do anti-fog coatings work?



Fog

Clear



Microdroplets form on the lens, blocking vision

Anti-fog coating reduces droplet contact angle

Forming a film to allow light to pass through

Fast facts... did you know?

- Protective eyewear coatings can feature both fog and scratch-resistance
- Most 3M™ Anti-Fog Coatings are applied to both sides of the lens, helping to increase anti-fog performance across a range of environments




Anti-Fog Performance

Hazards vary by job, which is why 3M offers three different anti-fog coatings, allowing workers to select the option that meets their needs.




Anti-fog Performance

Resistance to fogging during first use




Anti-fog Performance

After soaking in water for 1-2 hours*




Anti-Scratch Performance

After falling sand abrasion**




Coating Coverage/ Application to Lens



Wash Durability

with limited change to performance




Work Environments



Meets ANSI/ISEA Z87.1 "X" and EN166 "N" Anti-Fog Requirements



Meets EN166 "K" Resistance to Abrasion by Fine Particles



* as per ANSI Z87.1/EN166 test protocol
** as per EN166 test protocol

For more information:

3M United Kingdom PLC
3M Centre
Cain Road
Bracknell
RG12 8HT
Health & Safety Helpline: 0870 60 800 60
www.3M.co.uk/safety

3M Ireland Limited
The Iveagh Building
The Park
Carrickmines
Dublin 18
Ireland
Health & Safety Helpline: 1 800 320 500