PAYMENT PROCESSOR





72425 - Connect PayCase 5500

PAYMENT PROCESSOR

IPORT CONNECT PayCase Manual

Thank you for purchasing the all-new IPORT CONNECT Platform. We hope you enjoy this revolutionary new system, and if at any time you need more assistance, please get in touch with IPORT Tech Support via Online chat or through

our help desk online.

- IPORT Team

Whats in box:

- 1 IPORT CONNECT Paycase for Moby 5500 Processor
- 1 IPORT Security Tool
- 1 Info Card
- 2- Hex head screws

Glossary of Terms:

 Payment Processor Dock - The Finished stationary dock providing power and a mounting

location for a Payment Processor Case


 Payment Processor Case - The removable housing providing charging and mounting for a Ingenico MOBY 5500 payment processor.


• Security Foot - The metal removable portion of the Payment Processor Dock allowing for a secure mounting of the Payment Processor Dock when screwed to a solid surface.

PAYMENT PROCESSOR

IPORT CONNECT Paycase 5500

1. Remove the Moby 5500, and PayCase from their packaging.








Moby 5500 PayCase 5500

PAYMENT PROCESSOR

2. Use the IPORT Security tool to ensure the PayCase is not locked by sliding the lock up the Unlock position.









PAYMENT PROCESSOR

3. Separate the two halves of the PayCase, revealing the USB-C cable for the Payment Processor.




PAYMENT PROCESSOR

4. Move the USB-C Cable down and out of the way of the incoming Payment Processor to avoid damage to the USB-C connector.



PAYMENT PROCESSOR


5. Slide the Payment Processor mag strip and chip reader away from the USB-C connector.



PAYMENT PROCESSOR

6. Insert the USB-C connector into the Payment Processor and ensure the cable is securely seated into the USB-C port.






IPURT CONNECT


PAYMENT PROCESSOR

7. Insert the PayCase side cover onto the exposed side of the Payment Processor. Ensure the case is in the Un locked location from Step 2, and securely snap in the top, middle, and bottom portions of the side cover.




PAYMENT PROCESSOR

8. Use the IPORT security tool to install the two provided hex head screws into the short side of the PayCase.




PAYMENT PROCESSOR

9. Turn the PayCase to the opposite side and use the provided IPORT tool to slide the lock on the back down into the Locked position.



PAYMENT PROCESSOR

10. Place the PayCase into the Station interface of a Connect PRO Case.



PAYMENT PROCESSOR

11. To lock the Paycase to the CONNECT PRO Case, insert the provided IPORT tool into the side of the Paycase and slide it up towards the lock icon.

