



Firmware Update for Certain Pioneer In-Dash AV Receivers

January 30, 2026

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update for **only for the following Pioneer In-Dash AV Receivers sold in the United States and Canada. Installation on any other product could cause irreversible damage.**

DMH-WT6000NEX
DMH-WT5000NEX

This firmware update corrects the following matters.

- Improves the usability of the radio preset channel list.
- Minor bug fixes

To perform this update, the following items are needed:

- One of the above Pioneer In-Dash AV Receivers
- Blank USB storage device (no files), 512 MB or larger in capacity, formatted to FAT32 or NTFS.

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take about fifteen minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
<https://usa.pioneer/pages/support>
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through <https://usa.pioneer/pages/contact>.

Sincerely,

Pioneer Electronics (USA) Inc.