






HEKMAN

A HOWARD MILLER COMPANY

ASSEMBLY INSTRUCTIONS

25840 - Desk

NO.	Hardware List		Q'ty
A		Bolt M6 * 40mm L	10
B		Spring Washer M6	10
C		Flat Washer M6	10
D		Wrench L 4	1



PLACE THE DESK TOP UPSIDE DOWN ON SOFT AND CLEAN SURFACE TO PREVENT SCRATCHING

1. PULL OUT THE DRAWERS AT THE ENDS
2. ASSEMBLE THE END ASSEMBLIES TO THE DESK TOP USING BOLT (A), SPRING WASHER (B), AND FLAT WASHER (C) TIGHTEN WITH WRENCH (D)
3. SET THE DESK UPRIGHT, ASSEMBLY COMPLETE

MADE IN INDONESIA