









HEKMAN®

X A HOWARD MILLER COMPANY

79188 TABLE DESK

HARDWARE LIST					
A	B	C	D	E	
ALLEN BOLT 3/16" X 2" (10 PCS.)	FLAT WASHER M8 (10 PCS.)	SPRING WASHER M8 (10 PCS.)	SCREW Ø6 X 3/4" (2 PCS.)	ALLEN KEY L5 (FOR ALLEN BOLT) 1 PC.	
					

PART INSIDE	
1	2
TOP ASSEMBLY (1 Pc)	LEGS (2 Pcs)
	

Assembly Instruction

STEP 1.

LAY TOP ASSEMBLY OF THE TABLE DESK UPSIDE DOWN ON A SOFT, CLEAN AND FLAT SURFACE. PULL OUT DRAWERS ON SOFT MATERIAL TO PREVENT SCRATCHING SURFACE.

STEP 2.

ALIGN LEG (2) TO HOLES IN THE TOP ASSEMBLY (1) AND CONNECT USING FLAT WASHER (B), SPRING WASHER (C), ALLEN BOLT (A) AND ALLEN KEY (E) PROVIDED. DO NOT FULLY TIGHTEN THE BOLTS UNTIL THE STRETCHER IS ATTACHED.

STEP 3.

ATTACH STRETCHER USING A SCREW (D) WITH SCREW DRIVER (NOT INCLUDED).

STEP 4.

TIGHTEN ALL BOLTS HOLDING THE LEG ASSEMBLIES TO THE TOP ASSEMBLY.

STEP 5.

SET DESK UP RIGHT INSTALL THE END DRAWERS.

