


ASSEMBLY INSTRUCTION


TEMPERED GLASS METAL BAR CART

A Glass



2pcs

B Top Frame



1pc

C Stretcher




2pcs

D Stretcher



2pcs

E Bottom Frame



1pc

F Caster



4pcs

G Bolt
Ø1/4"x1/2"



8pcs

H Allen Key
M4




1pc

I Spanner
M17




1pc




This page lists all the contents included in the box. Please take the time to identify the hardware as well as the individual components to this product. As you unpack and prepare for assembly, place the contents on a carpeted or padded area to protect them from damage.


1 Attach the Caster (F) to the Bottom Frame (E) by Spanner (I).




2 Attach the Stretcher (C) and Stretcher (D) to Bottom Frame (E) using Bolt (G) by Allen Key (H).



- 3** Attach Top Frame (B) to Stretcher (C) and Stretcher (D) using Bolt (G) by Allen Key (H) as below shown.



- 4** Put Glass (A) on Top Frame (B) and Bottom Frame (E) as below shown.



Cleaning & Care

Treat surface with care. Surface is resistant to scratches but is not scratch resistant. Clean surfaces with a dry or damp soft cloth. Do not use abrasive cleaners. Hardware may loosen over time. Periodically check that all connections are tight.