


HEKMAN

X A HOWARD MILLER COMPANY

ASSEMBLY INSTRUCTIONS

25204 - END TABLE



PLACE THE END TABLE UPSIDE DOWN ON SOFT AND CLEAN SURFACE TO PREVENT SCRATCHING

1. ATTACH THE FOUR LEGS (#1) TO THE TABLE TOP
2. ASSEMBLE THE X STRETCHER TO THE FOUR LEGS (#1), WITH FEET (#2)
3. SET THE END TABLE UPRIGHT

MADE IN INDONESIA