



Important Firmware Update for Pioneer DMH-260BT In-Dash AV Receivers

April 22, 2025

Dear Valued Pioneer Customer:

We would like to inform you of the availability of an important firmware update **only for Pioneer DMH-260BT In-Dash AV Receivers sold in the United States. Installation on any other product could cause irreversible damage.**

This firmware update corrects the following issue.

- Fixes a problem where a watermark is displayed on the Android Auto screen.

To perform this update, the following items are needed:

- Pioneer DMH-260BT In-Dash AV Receiver
- Blank USB storage device (no files), 2 GB or larger in capacity, **must be formatted to FAT32.**

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take about four minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
<https://usa.pioneer/pages/support>
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through <https://usa.pioneer/pages/contact>.

Sincerely,

Pioneer Electronics (USA) Inc.