



Components & Hardware List






Keep the top ring on clean surface with assembly showing upwards. Following the direction arrows marked on ring and legs, place the legs (A,B,C) with corresponding grooves marked (A,B,C) on the ring. Secure the legs with help of allen Screws. Fasten all screws partially.









Now tighten the top ring allen screws upto 100%.







Now align the holes (D, E & F) of base structure to the holes (D, E & F) in top. Start tightening the screw into the hole D upto 50% and follow the same for E and F holes, now in second round tighten the screws upto 80% in the same sequence and in third round tighten the screws upto 100%.

Assembled View

Note: In this assembly process, help of two persons is recommended.