

ELECTRONIC FUEL INJECTION TEST LIGHT (NOID LIGHT)


W89500

CONTENTS:

#W85101	GM TBI	#W85104	GM PFI
#W85102	BOSCH PFI	#W85105	GEO TBI
#W85103	FORD TBI	#W85106	GM SCPI

INSTRUCTIONS:

1. Disconnect harness connector from injector.
2. Plug test light into connector and start engine.
Flashing light indicates electrical system is functioning correctly.
Steady light or no light indicates malfunctioning electrical system.
If problem persists, check fuel system.



REPLACEMENT PARTS:

W85101	GM TBI
W85102	Bosch PFI
W85103	Ford TBI
W85104	GM PFI
W85105	Geo TBI
W85106	GM SCPI

For replacement parts
call 1-800-497-0552

PT
Performance Tool

P.O. Box 88259 • Tukwila, WA 98138 • 1-800-497-0552 • Made in Taiwan • © Copyright 2018 • www.wilmarcorp.com