



See safety datasheet (if applicable) and product label for safety information, handling and proper use.

Directions for Use

Hold sprayer six to eight inches from surface to be cleaned. Simply spray product on, and wipe away with sponge, cloth, or paper towel. For large surfaces, start at the bottom and work up. Heavily soiled surfaces may require agitation with a scrub pad and rinsing. NOTE: Do not use on or near uncured painted surfaces; cleaner vapors may cause discoloration. Do not use on aluminum or copper.

The most aggressive, ready-to-work spray and wipe cleaner we've ever made. Spray Clean HD goes to work quickly to eliminate the toughest dirt, grease, and grime. It removes a variety of stubborn stains and marks such as fingerprints, rubber marks, lipstick, pencil, crayon, hair and body oils, grease, shoe polish, smoke film, and many others.

Features & Benefits

Pleasant mountain berry fragrance will leave your facility smelling great

Works instantly on contact and on a multitude of surfaces

Just spray, wipe, and go!

Item Number & Unit of Measure

Item Number	HIL0011906
Unit of Measure	1 gal Bottle

Specifications

Color	Purple
Appearance	Clear
Fragrance	Mountain Berry
Formula Type	Liquid
Dilution Ratio	RTU
PH	10.50 - 11.50
Non-Volatile Matter	1.50 - 2.00%

Safety