



Extended Warranty
Sign Up

E-1

Welcome home!

ELG-676

**TEAMSON HOME
Stratford FC 2 Doors**





Questions? Comments? Need help?
Call or email us any time!

Global Customer Service

USA

+1(800)935-3959

Mon - Fri 10:00am ~ 2:00pm EST

✉ support@teamson.com

EU/UK

+44(0)1952-916-050

Mon - Thu 9:00am ~ 5:00pm GMT

Friday 9:00am ~ 4:00pm GMT

✉ support@teamson.co.uk

ASIA

深圳办公室:

+86(0755)8885-3558.分机号331

Mon - Sat 9:00am ~ 5:00pm GMT+8




✉ sales_ec@teamson.com

台北办公室:

+886(2)2556-6268


Mon - Fri 9:00am ~ 5:00pm GMT+8

✉ sales_ec@teamson.com



** Got questions? Please have your product code (on the first page of this instruction, e.g. TD-12345A) and the order number ready, give us a call or email us through our customer care support! We are always ready to assist you!


Exploded Drawing



**Scan for assembly
instructions.**


Product Parts

A




1 PC

B




1 PC

C



1 PC

D



1 PC

E




1 PC

F




1 PC

G



2 PCS

H



1 PC

I



2 PCS

J



1 PC

! Care Instructions

Dust surface with a dry soft cloth. Do not use window cleaners or cleaning abrasives as they will scratch the surface and could damage the protective coating

! WARNING


Small parts and sharp edges may be present prior to assembly.



Scan for assembly instructions.


Hardware

1



8 PCS


2



Ø15*12

8 PCS


3



Ø8*30mm

12 PCS

4



Ø3*12mm


8 PCS

5



8 PCS


6



Ø3*12 D=7


16 PCS

7




2 PCS

8



2 PCS

9




1 PC

10



1 PC

11



Ø4*25mm

2 PCS

12





2 PCS






Scan for assembly instructions.


Step 1



Scan for assembly instructions.

Step 2


- 1  4 pcs 2  4 pcs 3  4 pcs
- Ø15*12 Ø8*30mm



Scan for assembly instructions.


Step 3

6




ø3*12 D=7

16 pcs







Scan for assembly
instructions.



Step 4



Scan for assembly instructions.

Step 5

- 9**  1 pc
 10  1 pc
 11  $\phi 4 \times 25$ 2 pcs
 12  2 pcs



Scan for assembly instructions.