

QUESTION

Figure 1 shows a rectangular plate with a hole. The plate has a width of 100 mm and a height of 100 mm. The hole has a diameter of 50 mm and is centered on the plate. The plate is subjected to a uniform stress of 100 MPa.

Find the stress concentration factor K_t .



100 mm