



BOSCH

BRING THE HEAT

Heated workwear for on and off the jobsite

GHH12V-20



THREE HEAT LEVELS FOR CONTROL AND COMFORT

Provides the right temperatures regardless of the weather



SPECIALLY DESIGNED LIGHTWEIGHT FABRIC

Allows for easy care plus warmth and durability in rough jobsite conditions



12V MAX PORTABLE POWER ADAPTER

Delivers power for heat and fast charging to phones and other mobile USB devices



WASHER AND DRYER SAFE

Easy care for long life; see care instruction for details

COMPLETE COVERAGE AND PROTECTION

with large adjustable hood

THREE HEAT SETTINGS



LOW

25% POWER FOR 420 MIN*



MEDIUM

50% POWER FOR 228 MIN*



HIGH

100% POWER FOR 138 MIN*

*Runtime for Bosch BAT414 12V Max 2.0 Ah battery

[LEARN MORE](#)

www.boschtools.com

12V MAX

VERSATILE ASSORTMENT OF 12V SOLUTIONS

Delivering high performance in a manageable size from recip saws, hammer drills, impact drivers, oscillating multi-tools to laser levels, lights and more.



12V MAX HEATED HOODIE

GHH12V-20

VERSATILE DESIGN

Standalone warmth on brisk days, ideal mid-layer for coldest conditions

THREE ZIPPERED POCKETS

Provide secure storage

SPECIALLY DESIGNED LIGHTWEIGHT FABRIC

Allows for easy care plus warmth and durability in rough jobsite conditions



WASHER AND DRYER SAFE

Easy care for long life; see care instruction for details



FITTED SLEEVES AND WAIST

Keep warmth in, cold out



LARGE ADJUSTABLE HOOD

Complete coverage and protection from the cold

THREE HEAT LEVELS FOR CONTROL AND COMFORT

Provides the right temperatures regardless of the weather



THREE QUICK-WARMING CORE HEAT ZONES

Includes two chest zones and one lower back zone providing thorough and efficient heat distribution

12V MAX PORTABLE POWER ADAPTER
Delivers power for heat and fast charging to phones and other mobile USB devices



Specifications

Voltage	12V Max (w/ GAA12V-21)
Material	Cotton and Polyester
Color	Black
Heat Levels	3
Heat Zones	3 (right/left chest, lower back)
Heat-Up Time	3 minutes
Max Runtime	7 hrs. (w/ 12V Max 2.0 Ah battery)
Sizes	Small-3Xlarge

Includes

GHH12V-203XLN12	GHH12V-203XL 12V Max Heated Hoodie; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHH12V-20XXLN12	GHH12V-20XXL 12V Max Heated Hoodie; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHH12V-20XLN12	GHH12V-20XL 12V Max Heated Hoodie; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHH12V-20LN12	GHH12V-20L 12V Max Heated Hoodie; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHH12V-20MN12	GHH12V-20M 12V Max Heated Hoodie; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHH12V-20SN12	GHH12V-20S 12V Max Heated Hoodie; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger

HEATED OUTDOOR GEAR FOR WORK AND LEISURE


For the perfect fit, consider the following criteria:

CHEST CIRCUMFERENCE

Measure horizontally around the widest area of your chest

ARM LENGTH

Measure from your wrist up to your shoulder



SIZE	S	M	L	XL	2XL	3XL
Chest	35"-37"	37"-38"	39"-40"	41"-42"	42"-44"	44"-45"
IN/CM	90-93	94-97	98-102	103-106	107-110	111-114
Arm Length	24"-25"	24"-25"	25"-26"	25"-26"	26"-27"	26"-27"
IN/CM	61-63	62-64	63-65	64-66	65-67	66-68



BOSCH



Robert Bosch Tool Corporation
1800 W. Central Rd.
Mount Prospect, IL 60056
www.boschtools.com

2021-149