



BOSCH

BRING THE HEAT

Heated workwear for on and off the jobsite

GHV12V-20



THREE HEAT LEVELS FOR CONTROL AND COMFORT

Provides the right temperatures regardless of the weather



SPECIALLY DESIGNED LIGHTWEIGHT FABRIC

Allows for easy care plus warmth and durability in rough jobsite conditions



12V MAX PORTABLE POWER ADAPTER

Delivers power for heat and fast charging to phones and other mobile USB devices



WASHER AND DRYER SAFE

Easy care for long life; see care instruction for details

Enhanced LIGHTWEIGHT DESIGN

THREE HEAT SETTINGS



LOW

25% POWER FOR 420 MIN*



MEDIUM

50% POWER FOR 228 MIN*



HIGH

100% POWER FOR 138 MIN*

*Runtime for Bosch BAT414 12V Max 2.0 Ah battery

[LEARN MORE](#)

www.boschtools.com

12V MAX

VERSATILE ASSORTMENT OF 12V SOLUTIONS

Delivering high performance in a manageable size from recip saws, hammer drills, impact drivers, oscillating multi-tools to laser levels, lights and more.



12V MAX HEATED VEST

GHV12V-20

VERSATILE DESIGN

Lightweight flexible material, strategically placed heating elements, extended length for full torso coverage and more

THREE QUICK-WARMING CORE HEAT ZONES

Includes two chest zones and one lower back zone providing thorough and efficient heat distribution

RUGGED OUTER SHELL

Made from 100% wind- and water-resistant polyester

FIVE POCKETS FOR OUTSTANDING STORAGE

Includes interior large document pocket

12V MAX PORTABLE POWER ADAPTER

Delivers power for heat and fast charging to phones and other mobile USB devices



HIGH FOLD-OVER COLLAR

Fully zips around the neck to help protect from cold winds

THREE HEAT LEVELS FOR CONTROL AND COMFORT

Provides the right temperatures regardless of the weather



FITTED SHOULDER CUFFS AND ADJUSTABLE WAIST

For maximum comfort and coverage while working or playing

WASHER AND DRYER SAFE

Easy care for long life; see care instruction for details




Specifications

Voltage	12V Max (w/ GAA12V-21)
Fabric	Softshell
Material	Polyester and spandex
Color	Black
Heat Levels	3
Heat Zones	3 (right/left chest, lower back)
Heat-Up Time	3 minutes
Max Runtime	7 hrs. (w/ 12V Max 2.0 Ah battery)
Sizes	Small - 3Xlarge

Includes

GHV12V-203XLN12	GHV12V-203XL 12V Max Heated Vest; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHV12V-20XXLN12	GHV12V-20XXL 12V Max Heated Vest; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHV12V-20XLN12	GHV12V-20XL 12V Max Heated Vest; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHV12V-20LN12	GHV12V-20L 12V Max Heated Vest; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHV12V-20MN12	GHV12V-20M 12V Max Heated Vest; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger
GHV12V-20SN12	GHV12V-20S 12V Max Heated Vest; GAA12V-21 12V Max Portable Power Adapter; 12V Max Lithium-Ion 2.0 Ah Battery, 12V Max Charger

HEATED OUTDOOR GEAR FOR WORK AND LEISURE



For the perfect fit, consider the following criteria:

CHEST CIRCUMFERENCE

Measure horizontally around the widest area of your chest

ARM LENGTH

Measure from your wrist up to your shoulder

SIZE	S	M	L	XL	2XL	3XL
Chest IN/CM	35"-37" 90-93	37"-38" 94-97	39"-40" 98-102	41"-42" 103-106	42"-44" 107-110	44"-45" 111-114
Arm Length IN/CM	24"-25" 61-63	24"-25" 62-64	25"-26" 63-65	25"-26" 64-66	26"-27" 65-67	26"-27" 66-68



BOSCH



Robert Bosch Tool Corporation
1800 W. Central Rd.
Mount Prospect, IL 60056
www.boschtools.com

2021-148