










# HEKMAN<sup>®</sup>

**X** A HOWARD MILLER COMPANY

## 28449 WRITING DESK


HARDWARE LIST					
A	B	C	D	E	
ALLEN BOLT M6x15 mm (2 Pcs)	ALLEN BOLT M6x40 mm (8 Pcs)	FLAT W. M6 (10 Pcs)	LOCK W. M6 (10 Pcs)	ALLEN KEY L4 (FOR BOLT M6) 1 Pc.	
					

PART INSIDE		
1	2	3
TOP ASSEMBLY (1 Pc)	LEG ASSEMBLY (2 Pcs)	STRETCHER (1 Pc)
		

### Assembly Instruction

#### STEP 1.

LAY TOP ASSEMBLY UPSIDE DOWN ON A SOFT, CLEAN AND FLAT SURFACE. ASSEMBLE THE TOP ASSEMBLY (1) AND THE LEG ASSEMBLY (2) WITH ALLEN BOLT (B), LOCK WASHER (D), FLAT WASHER (C) USE ALLEN KEY (E).



#### STEP 2.

ASSEMBLE THE STRETCHER (3) TO THE LEG ASSEMBLY (2) WITH ALLEN BOLT (A), LOCK WASHER (D), FLAT WASHER (C) USE ALLEN KEY (E) AND TIGHTEN ALL THE BOLT.