




X A HOWARD MILLER COMPANY

ASSEMBLY INSTRUCTION FOR 26106 CHAIRSIDE TABLE

HARDWARE LIST			
NO.	ITEM	DESCRIPTIN	QTY.
1		JCB Bolt M6X16 MM	20
2	0	Flat washer M8X22 MM	8
3		Allen wrench	1







TO ASSEMBLY:

- STEP 1: Unpack chairside table and turn the top assembly (A) upside down. on a clean, soft surface.
- STEP 2: Match the iron legs(B). use matching marks A1,A2 & B1,B2 on top assembly (A) & shelf (C).
- STEP 3: Align holes in legs (B) with holes on bottom of table (A)& shelf (C) and slide it into position.
- $STEP\ 4: Thread\ the\ flat\ washer (2)\ , JCB\ bolt\ (1)\ to\ leg\ (B)\ .\ Do\ not\ tighten\ bolts\ fully\ until\ all\ bolts\ are\ started.$
- STEP 5: Tighten bolts in step 4 fully with allen wrench (3) then carefully turn the chairside table upright.