




X A HOWARD MILLER COMPANY

ASSEMBLY INSTRUCTION FOR 23707 CHAIR SIDE TABLE

HARDWARE LIST			
NO.	ITEM	DESCRIPTIN	QTY.
1		JCB Bolt M6 X 20MM	12
2	0	Flat washer M6X18 MM	12
3		Allen wrench	1







TO ASSEMBLY:

STEP 1: Unpack chair side table and turn the top (A) upside down .

STEP 2: Align holes in legs (B) with holes on bottom of top (A) and slide it into position.

STEP 3: Thread the flat washer(2), JCB bolt (1) to leg (B). Do not tighten end assemblies fully. STEP 4: Tighten bolts in step 3 fully with allen wrench (3) then carefully turn the table upright.