OUICK START SETUP GUIDE



FOR DAHLE SHREDDERS

• UNPACK THE SHREDDER • REMOVE SHIPPING/TRANSPORT BOLTS • FILL AUTOMATIC OILER

QUICK START- SETUP GUIDE

UNPACK THE SHREDDER

- Cut the shipping straps and remove the top box cover.
- Lift & remove the corrugated box sleeve surrounding the shredder and all packing material.
- Carefully lift the shredder out of the bottom corrugated base. (Please note - this shredder is suspended on the box and is top heavy. Carefully support the shredder while moving to avoid tipping over.)

REMOVE THE SHIPPING/TRANSPORT BOLTS

- Open the shredder door & remove the suspended waste bag.
- Locate the two (or three) recessed shipping bolts inside the cabinet, directly under the cutting head, and remove them. (*A hex key is provided for your convenience.*)

FILL THE AUTOMATIC OILER (if applicable)

- Open the cabinet door. If your shredder is equipped with an automatic oiler it will be located on the inside left of the machine.
- Slide open the reservoir & unsrew the black fill cap.
- Pour the oil into the reservoir, tighten the cap, and slide back into shredder.

POWER ON THE SHREDDER

- Install the power cord *(located inside the cabinet)* on the back of the machine & plug it in.
- Be sure the top of the red emergency shutoff switch is depressed.
- Press the bottom button on the round command dial (*located on the top cover of the machine*). This will turn the shredder on.

Dahle North America, Inc. 49 Vose Farm Road Peterborough, NH 03458 (800) 995.1379 / www.dahle.com



Please see Owner's Manual for complete operating instructions







