


HEKMAN

A HOWARD MILLER COMPANY
Grand Rapids, Michigan

OFFICE CHAIR ASSEMBLY INSTRUCTION MODEL 79257B



1. Position the Steel Sleeve into the Base Assembly.
2. Push the bottom of the Gas Lift into the center hole of the Base Assembly until it is tight.
3. Slide the Plastic Sleeve over the Gas Lift.
4. Push the Seat Assembly onto the Gas Lift by aligning the top of the Gas Lift with the center hole on the underside of the Seat Assembly.

Periodically check that all the connections are tight and secure.
Maximum Weight capacity = 300 pounds