

# Fiber Optic Cleaning Kits

optimize!  
**softing**

# XpertClean

Fiber optic cleaning is always required before connecting and before testing a fiber optic cable. In the past, gathering the right set of cleaning supplies, and understanding their use, required time and research. With Softing CleanMachine push and click cleaners for bulk cleaning, and CleanSlide for specialty connectors such as APC, fiber optic cleaning is easy. The XpertClean process saves you time cleaning and troubleshooting resulting in clean fiber optic end faces and maximum network performance.



## Product Description

The **CleanMachine** is the easy to use cleaning tool for fast and reliable end face cleaning. End faces in bulkheads or on cable assemblies are both effortlessly cleaned the first time, every time. The CleanMachine has an easy to use mechanism that advances fabric over a cleaning tip with just a short push and click of the tool.



Part number:  
XC-AC-CMACH-STSCFC

- for 2.5 mm connectors
- ST, SC, and FC connectors



- Cleans connectors on backplane and on jumpers
- Part of the XpertClean process for first time cleaning, every time
- Used to meet or exceed IEC 61300-3-35, IEC TR62627-01, and Telcordia GR-2923-CORE and SAE
- Aerospace AIR6031
- Effective for the widest range of contaminants
- Easy to use for quick and reliable cleaning
- Rugged and durable. Great for all work sites.
- Magnetic backing for easy rack placement
- Over 800 clicks per 2 mm and 1.25 mm machine

## Typical Applications

- End face connector cleaning
- Cleaning patchcord connectors
- Cleaning bulk-head connections
- Blue CleanMachine is made for 2.5 mm SC, ST, FC connectors
- Orange CleanMachine is made for 1.25 mm LC connectors

## XpertClean Process for CleanMachine

### Usage Instructions

Insert the CleanMachine tip into the connector, and push in the tool 2-3 clicks advancing the fabric, perfectly cleaning the end face. The XpertClean process eliminates all debris and contamination the first time, avoiding expensive rework and truck-rolls from bad connections.



## Fiber Cleaning Supplies for LC, ST, SC, FC, MU, PC, and APC connectors

Part number:

**XC-AC-CMACH-STSCFC**

- for 2.5 mm connectors
- ST, SC, and FC connectors



Part number:  
**XC-AC-CSLIDE**

- for APC, PC, or MU connectors



Part number:

**XC-AC-CMACH-LC**

- for 1.25 mm connectors
- LC connectors

### Contact:

#### NORTH AMERICA

Softing Inc.  
2332 News Sentinel Dr  
Knoxville, TN 37921

E-mail: [sales.us@softing.com](mailto:sales.us@softing.com)

Phone: +1.865.251.5252

### XpertClean for LC, ST, SC, FC, MU, PC, APC Fiber Optic End Faces

CleanMachine for 1.25 mm LC connectors, **XC-AC-CMACH-LC**  
CleanMachine for 2.5 mm SC, ST, FC connectors, **XC-AC-CMACH-STSCFC**  
CleanSlide for SC, FC, ST, MU, PC, and APC, **XC-AC-CSLIDE**