


ASSEMBLY INSTRUCTIONS

X A HOWARD MILLER COMPANY

25200 / 25400 - SMALL COFFEE TABLE

NO.	Hardware List		Q'ty
A	<u> </u>	Screw 6 $x^{5/8}$ "	8



PLACE THE SMALL COFFEE TABLE UPSIDE DOWN ON SOFT AND CLEAN SURFACE TO PREVENT SCRATCHING

- 1. ATTACH THE FOUR LEGS (#1) TO THE TABLE TOP
- 2. SECURE THE FOUR LEGS WITH SCREW (A) INTO THE METAL BRACKET *SCREW DRIVER NOT INCLUDED
- 3. ASSEMBLE THE X STRETCHER TO THE FOUR LEGS (#1) WITH FEET (#2)
- 4. SET THE SMALL COFFEE TABLE UPRIGHT AND PUT THE TOP GLASS ON THE SURFACE FRAME
- 5. ASSEMBLY COMPLETE

MADE IN INDONESIA