

[ASIX MCS7715] USB to Serial Parallel Adapter Installation Guide

This guide contains installation instructions for the following operating systems:

1. [Windows \(EXE\)](#)
2. [Windows \(INF\)](#)

[ASIX MCS7715] USB to Serial Parallel

Adapter Installation for Windows

Install Guide

Prior to installing this device, ensure that your operating system is up to date (for example, you have installed the most recent service pack).

To install the driver:

1. Right-click the zip folder that you downloaded, select **Extract All**, and follow the on-screen instructions.
2. Select the appropriate folder for your operating system.
3. Right-click **Setup.exe**.
4. Click **Run as Administrator**.

Note: If the **Run as Administrator** option is not available, you might be attempting to run the installer from within the zipped file. Extract the files using the instructions in Step 1.

5. Follow the on-screen prompts to install the device drivers and restart the computer when prompted.
6. Your computer will automatically complete the driver installation and your device should be ready to use.

[ASIX MCS7715] USB to Serial Parallel

Adapter Installation for Windows

Install Guide

1. Right-click the zip folder that you downloaded, click **Extract All**, and complete the instructions.
2. Press the **Windows** key + **R**, type **devmgmt.msc**, and press **Enter** to open the Device Manager.
3. Right-click **PCI Serial Port**, which will have a "!" or "?" next to it to indicate a driver issue.
4. Click **Update Driver**.
5. Click **Browse my computer for driver software**.
6. Select the **Let me pick from a list of device drivers on my computer** option.
7. On the **Select your device's type from the list below** screen, click **Show All Devices**, and click **Next**.

Note: The **Select your device's type from the list below** screen does not appear on all systems. If you do not see this screen, skip this step.

8. Select the **Have Disk** option.
9. Browse to the **Drivers** folder and open the **32-bit** or the **64-bit** folder, depending on your system type.

Note: To view your system type, press **Windows** key + **R**, type **control /name microsoft.system**, and press **Enter**.

10. Click the **StnMF** file or the **NmXpMf** file (only one of the file names is displayed). Click **OK**, and then click **Next**.
11. The COM ports are listed in Device Manager under **Ports (COM & LPT)**. Repeat steps 3 to 10 for each of the COM ports, selecting the **StnPorts** file or the **NmPorts** file in step 10.