

VIA® USB 3.0 Driver Package Release Notes

2012-02-08

[Support Platforms](#)[Component version inside this package](#)[Notices](#)[Update of this Release](#)[Update History](#)[Installation and Uninstall](#)[Known Issues](#)[Limitations](#)[Revision History](#)[DISCLAIMER](#)

Support Platforms

Hardware:

VIA XHCI Host Controller

Operating System:

Microsoft Windows® 7 X86/X64 and Windows XP X86/X64

[Back to top](#)

Component version inside this package

Component	Version
VIA USB 3.0 Driver for Windows 7	Port Driver (Xhcdrv.sys): 6.1.7600.1902 Hub Driver (Viahub3.sys): 6.1.7600.1902
VIA USB 3.0 Driver for Windows XP	Port Driver (Xhcdrv.sys): 6.1.7600.1902 Hub Driver (Viahub3.sys): 6.1.7600.1902

[Back to top](#)

Notices

1. Please update your VIA XHCI host controller PCIe Card with latest version of firmware before install this driver.

[Back to top](#)

Update of this Release

1. Fixed USB 2.0 storage device performance drop issue.
2. Fixed can't recognize Samsung Galaxy Tab issue.

[Back to top](#)

Update History

[Back to top](#)

Installation and Uninstall

1. Please update your VIA XHCI Host Controller PCIe Card to latest version of firmware before you install this driver.

- Please use the setup program to install/uninstall the driver for XHCI host controller and its root hub device.
- Following is the instruction for silent mode driver installation/removal.

Command line	Execution
setup.exe -s	Silent install all included components but not reboot the computer.
setup.exe -s /z"reboot"	Silent install all component and reboot the computer.
setup.exe -s /z"reboot;remove"	Silent uninstall all include component and reboot the computer.
setup.exe -s /z"remove"	Silent uninstall all components but not reboot the computer.

[Back to top](#)

Known Issues

- Following is a list of USB devices which has compatible issue with this driver.
N/A

[Back to top](#)

Limitations

[Back to top](#)

Revision History

Version	Release Date	Comments
V1.00 A (WHQL)	2010-12-08	● VIA Windows 7 XHCI Driver (Logo'd)
V1.10 A (WHQL)	2010-12-31	● VIA Windows 7 XHCI Driver (Logo'd)
V1.20 A (WHQL)	2011-01-12	● VIA Windows 7 and Windows XP XHCI Driver (Logo'd)
V1.30 A (WHQL)	2011-03-02	● VIA Windows 7 XHCI Driver (Logo'd)
V1.40 A (WHQL)	2011-03-11	● VIA Windows 7, Vista and XP XHCI Driver (Logo'd)
V1.41 A (WHQL)	2011-03-21	● Update WinXP Logo'd driver
V1.50 A (WHQL)	2011-05-25	● VIA Windows 7 XHCI Driver (Logo'd)
V1.60 A (WHQL)	2011-05-31	● VIA Windows 7 XHCI Driver (Logo'd)
V1.60 B (WHQL)	2011-06-21	● VIA Windows 7, XP XHCI Driver (Logo'd)
V1.70 A (WHQL)	2011-09-06	● VIA Windows 7 XHCI Driver (Logo'd)
V1.80 C (WHQL)	2012-01-06	● VIA Windows 7 and Windows XP XHCI Driver (Logo'd)
V1.90 A (WHQL)	2012-02-08	● VIA Windows 7 and Windows XP XHCI Driver (Logo'd)

[Back to top](#)

DISCLAIMER

Information in this document is provided in connection with VIA USB 3.0 driver package. VIA Technologies assumes no responsibility for any errors in this document. Any part of document MUST NOT be reproduced, transmitted, or translated into any language, or in any form without the prior written permission of VIA Technologies Inc.

VIA may make changes to specifications and product descriptions at any time, without notice.

Copyright © VIA Technologies, Inc. 2009-2011

[Back to top](#)

All copyrights are reserved by VIA Technologies, Inc. <http://www.via.com.tw/en>